ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0245	NA	Houses
Segment No.	**Total Length (m)**	
10/S-W0245/S024646	48.40	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	48.40	77.557389	13.062774	77.557389	13.062337	Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Missing Covering Slabs at KNV 2nd Stage Kempanna Layout Venkatagiriyappa Layout in Ward No. 10 (Doddabommasandra).	1500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	constrution of RCC Drains and Providing Covering Slab	010-20-000090
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/20/2020-21	31/07/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/10/2021	29/10/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. Sumukha Core Tech (prop: Venkatesh Prasad H T)		0.00
Phone No.	**E-Mail ID**	
9620665793		

Sumitra. N K
AE/JIO

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0245	NA	Houses
Segment No.	**Total Length (m)**	
10/S-W0245/S024646	48.40	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	48.40	77.557389	13.062774	77.557389	13.062337	Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Missing Covering Slabs at KNV 2nd Stage Kempanna Layout Venkatagiriyappa Layout in Ward No. 10 (Doddabommasandra).	1500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	constrution of RCC Drains and Providing Covering Slab	010-20-000090
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/20/2020-21	31/07/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/10/2021	29/10/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. Sumukha Core Tech (prop: Venkatesh Prasad H T)		0.00
Phone No.	**E-Mail ID**	
9620665793		

Sumukha. AE
AE 10

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0247	4th Crs	Houses
Segment No.	**Total Length (m)**	
10/S-W0247/S024415	276.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	276.82	77.558008	13.062372	77.557146	13.060587	Main Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Providing Missing Covering Slabs at KNV 2nd Stage Kempanna Layout Venkatagiriyappa Layout in Ward No. 10 (Doddabommasandra).	1500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC Drain and Providing Covering Slab	010-20-000090
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/20/2020-21	31/07/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/10/2021	29/10/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. Sumukha Core Tech (prop: Venkatesh Prasad H T)		0.00
Phone No.	**E-Mail ID**	
9620665793		

Suvitha - NL
AE W10

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Swetha n r
Date of Inspection	**Remarks**	
25/11/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	26/11/2021	25/12/2021	As proposed
SE	Vijay Kumar Haridas	26/11/2021	25/12/2021	Forwarded
EE	Mohan Das H T	25/11/2021	25/12/2021	Approved
AEE	Shivakumar M Goudar	25/11/2021	25/12/2021	Verified
AE	Swetha N R	25/11/2021	25/12/2021	Mobile Veification Done
AE	Swetha N R	25/11/2021	25/12/2021	Forward

Swetha. N R
AE WIO